


The crucial PLUS in safety!

Connection to the future



ONE-BUTTON HANDLING

PLUS The classic "test button" is eliminated. Before every switch-on procedure and during operation a fully automatic verification is performed in order to check the correct supply conditions.




PLUS Switching on is only possible with bare hand. Measuring errors caused, for example, by the wearing of a glove when switching on are indicated by the signal unit flashing red. In this case, the PRCD-S+ from PCE gives a visual warning and does not switch on.

The PE conductor circuit is switched on in advance and switched off with a delay.



PLUS Failure situations like external voltage on the PE conductor or fault current above rated values cause an interruption of L and N. The PE conductor stays closed and keeps being monitored!

Overvoltage will be detected – the PRCD-S+ switches off or cannot be switched on.



PC Electric GesmbH

Diesseits 145, A-4973 St. Martin im Innkreis TEL +43 7751 61220 | office@pcelectric.at

www.prcd-s.info

